


|                |                               |    |       |               |        |
|----------------|-------------------------------|----|-------|---------------|--------|
| Group          | MACHINE COVER                 | 번호 | M_TLM | No. of sheets | 1 of 1 |
| Characteristic | Doosan tool monitoring system |    |       |               |        |

• 정의(Definition)

– The function for monitoring the overload in tool.

• 상세 설명(Description)

– This function checks the spindle and each axis load in real time for detect the tool's wear or breakage. It protect the danger of tool and holder.



Display on main operation panel

• 종류(Value)

1 set